





NOTES:

1. THE SAND BACKFILL, VALVE BOX AND COMPACTION IS INCIDENTAL
2. IF CONSTRUCTING A NEW GATE VALVE, IT MUST BE CONSTRUCTED DETAIL PLATE W-3